



TI-3525 1  
1 of 4  
J. Garner

# 1 Mask HD Cap Proposal



- Main Processing Issues:**
- A. HD Cap stack etch
  - B. Edge leakage
  - C. Al Cap coverage
  - D. Stack step height

Rost C021

TI Proprietary Information - Internal Data




FIG. 2A




FIG. 2B






FIG. 2C






FIG. 2F




FIG. 2G